

Indian Village MHP
Lead Service Line Inventory

Street Address	Town	Zip Code	Lead Gooseneck, Pigtail or Connector Currently Present?	Current Public Side SL Material ①	Was Public SL Material Ever Previously Lead?	Public SL Material Verification Method ①	Public SL Installation or Replacement Date	Public SL Size	Customer SL Material ①	Customer SL Material Verification Method ①	Lead Solder Present?	Building Type	POU or POE Treatment Present? ①	Customer SL Installation or Replacement Date	Customer SL Size	SL Category ①
419 Union Mills Rd, Lot 39	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 40	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 41	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 42	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Copper	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 43	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 44	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 45	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 46	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 47	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 48	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 49	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 50	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Copper	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 51	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 52	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 53	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 54	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 55	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 56	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 57	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 58	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead
419 Union Mills Rd, Lot 59	Broadalbin	12025	No	Plastic	No	Records		Upto 1"	Plastic	Records	No	Single Family	No		Upto 1"	Non-Lead

Indian Village MHP
Lead Service Line Inventory
Summary of Lead Service Line Inventory

I. System Information

Water System Name	Indian Village MHP
PWS ID Number	NY1701513

II. Contact Information for Owner / Licensed Operator of Record Completing the Form

Contact Name	Andrew Huisjen
Contact Phone Number	518-848-6479
Contact Email Address	info@heihomes.com

III. Summary of Inventory

Total Number of Service Lines in the Distribution System	61
Total Number of Identified Service Lines	61
Total Number of Lead Service Lines	0
Total Number of GSLRR	0
Total Number of Non-LSL	61
Total Number of Unknown Service Lines	0

Service Lines	Lead	GSL or GSLRR	Non-Lead	Unknown
PWS - Side Service Lines	0	0 GSL	61	0
Customer - Side Service Lines	0	0 GSL	61	0
Total Number of Service Lines in the Distribution System	0	0 GSLRR	61	0

Service Line Identification Methods

Identification Methods	PWS- Side SLs	Customer-Side SLs
Historical Records	61	61
Field Inspection	0	0
Customer Identification with Photo or other Verification	NA	0
Excavation	0	0
Sequential Sampling	0	0
Statistical Analysis/Predictive Model	0	0

IV. Inventory Availability - The inventory must be available to public

<p>If 50,000 customers or greater: Posting the inventory online water system's website.</p> <p>If under 50,000 customers: Explain how to access the inventory</p>	Address:
	website: www.heihomes.com

V. Certifications

<p><i>By submitting this form, I have verified and certify the information listed in this form is true and accurate to the best of my knowledge and belief.</i></p>		
<p>Andrew Huisjen</p> <hr/> <p>Name</p>	<p>Owner/Operator</p> <hr/> <p>Title</p>	<p>10/2/2024</p> <hr/> <p>Date</p>